

おおの あぶらさか いずみ あぶらさか



※表示は本線部分の進捗を表したものです
※模式図のため現場状況と一致しない場合があります



はこがせ

A B



法面ひび割れ
発生箇所

学識経験者による現地診断

しもはんばら

ひがしいちぬの

An aerial photograph showing the construction of a large dam or bridge structure. The structure is a tall, curved concrete wall with a series of horizontal buttresses. It is surrounded by dense green forest. At the base of the structure, there are construction vehicles, including yellow excavators, and a dirt road. The structure appears to be a dam, with a large reservoir behind it.